Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1181	73/762-769.ccls.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/10/27 15:55
L2	256	73/762,769.ccls.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/10/27 15:55
L3	0	(((stress strain load force pressure) near4 (sens$4 detect$4 indicat$4 monitor$5 measur$5 calculat$5 transducer gage gauge cell)) and ((second pair two "2" double couple plurality multipl$5 many several) near3 electrode) and (diamond near4 carbon) and (dielectric)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/10/27 16:01
L5	51	("4553124" "5263375" "5813280" "5492017" "5901591" "5950141" "5959215" "6066882" "4522066" "5365059" "4509370" "4599901" "4275599" "4339956" "4484480" "4784811" "4905523" "4969366" "4986137" "6004639" "4337665" "4402229" "4429579" "4558600" "4577100" "4838369" "5191949" "5288995" "5386442" "5410109" "5456724" "5472331" "5493113" "5503232" "5537883" "5540108" "5553504" "5659141" "5817951" "5822876" "5828724" "5886350" "5926584" "5985183" "5997780" "6038933" "6058160" "6105438" "6220104").pn.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/10/27 16:07

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L4	1	(((stress strain load force pressure) near4 (sens$4 detect$4 indicat$4 monitor$5 measur$5 calculat$5 transducer gage gauge cell)) and ((second pair two "2" double couple plurality multipl$5 many several) near3 electrode) and (diamond near4 carbon)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/10/27 16:01

Interference Search ⓐ 10/27/05